



Ford Motor Company Limited

Fuels & Lubes Department  
Ford Motor Company  
Dunton Technical Centre  
Room 15/GB-E10-B  
Laindon, Basildon,  
Essex, SS15 6EE

Tel.: + 44 (0) 1268 402801

Fax: + 44 (0) 1268 405619

Date: 17<sup>th</sup> January 2018

**DJALMA PALIN JUNIOR**  
Texsa Do Brasil LTDA  
AV. Florivaldo R. Tampelini,  
1470 – PQ.  
Industrial I-CEP:87507-070  
UMUARAMA  
Brazil,

Dear DJALMA PALIN JUNIOR,

**Ref: Request for Claiming Ford WSS-M2C913-D Specs on Texsa Ultrasynthese,  
SAE 5w-30 of Texsa Do Brasil using Lubrizol Formulation Code OS261405**

We acknowledge your claim for Ford WSS-M2C913-D Specs on Texsa Ultrasynthese, SAE 5W-30 based on Formulation Code OS261405 from Lubrizol.

However, please ensure that you adhere to these formulations including the additive types, additive treat rates and the base oils used for blending. Ford has the right to take samples, request analysis of the blends and have the right to ask you to remove the product from the market if requirements are not met.

Ford hereby excludes all liability whatsoever for our above acknowledgement and reserves our rights, as the testing has not been conducted by Ford and the acknowledgement was based only on the information provided.

**This acknowledgement from Ford in no way implies that Ford is recommending the oil. In no circumstances can any actual or implied recommendation be made to third parties.**

Yours sincerely,

**Suhair Abdelhalim**  
Senior Lubricant Engineer

**Rhys Davies**  
Fuels & Lubes Supervisor